IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 600111683-1 IN RE APPLICATION OF: U.S. Patent No. 7,055,925 **USPTO CONFIRMATION CODE: 9373** APPLICATION NO.: 10/632,011 FILED: Jul. 31, 2003 EXAMINER: Hai Pham **GROUP ART UNIT: 2861** FOR: CALIBRATION AND MEASUREMENT TECHNIQUES FOR PRINTERS 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS Sir The following is a request for a certificate of correction in Serial Number 10/632,011, now Patent Number 7,055,925. A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent. All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025. All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee

In column 13, line 21, in Claim 1, delete "loaning" and insert - - forming - -, therefor.

(Amendment to claims filed on Sep. 19, 2005, page 2, in Claim 1, line 2)

The requested corrections are attached on Form PTO 1050.

DATE:

Respectfully Submitted

Name: Steven R. Ormiston Registration No.: 35974

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.

: 7.055,925

APPLICATION NO.: 10/632,011

ISSUE DATE

: Jun. 06, 2006

INVENTOR(S)

: Francesc Subirada, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 13, line 21, in Claim 1, delete "loaning" and insert - - forming - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

This collection of information is required by 37 CFR 1322, and 1323, and 1324. The information is required to obtain or retain a benefit by the public which is to tile (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.